# WESTON FEDERAL PROGRAMS DIVISION HEALTH AND SAFETY PLAN EMERGENCY RESPONSE/SITE INVESTIGATION



SDMS DocID

1.	SITE INFORMATION
	TDD#: 9907-03 PCS#: 5472 Site Name: 12 th Street Land Fill Site
	Site Address: Street Number: Southwest of the intersection (ramps) E. 12th St. + I-49
	City/County/State/Zip Code: Wilmington, New Castle Conty, DF
	Site Contact / Telephone Number: Anne Biesland (302) 395 - 2610
	Site Directions (Attach Map): I-95 South into Delaura to I-495 South
	Take 12th street Exit. At end of ramp go right.
	Go 1/8-mile turn left into Assett Necovery services
•	parkinglot. At east end of pulling lot, go 300' down railroad Spor, Then west 200' to Brandywine Crux.
	railroad Spor, Then west 200' to Brandywine Cruex.
	Site is in woods along east side of Creek.
	Historical/Current Site Information: The site consists of 2 and parcels;
	19 and 14. along 12th Street. The city of Wilmington
	currently owns parcel 19 Parcel 14 is currently owned
	by the State of Delaware Both parcels were utilized
:	as manthorized dump sites, in which at least 100)
	55-gallon diving rusber hoses, slag, and a light colored
	ash-like material were disposed of on the property within
	The last 25-35 years.
•	
	Incident Type: ( ) Air Release: ( ) Spill:
	( ) Fire: (X) HW Site: Unau Thorized dump.
	Location: (X) Industrial ( ) Commercial ( ) Urban/Residential ( ) Rural
,	USEPA Contact: MIKE Towle SATA Site Leader: 7 421 Vavis
	Date of Initial Site Activities: 8 / 23 / 99 Site Health and Safety Officer: (b) (4)
	Original HASP?: Yes No Modification Number: 1 2 3 4 5

## 2. RESPONSE ACTIVITIES / DURATION

	Emergency l	Response		Assess	sment `
	( ) Perimeter Recon	hours	days	(⊀) Perimeter Recon	hours days
	( ) Site Entry	hours	days	( 💢 ) Site Entry	hours days
•	( ) Visual Documentation	hours	days	(x) Visual Documentation	4 hours days
	( ) Multi-Media Sampling	hours	days	(≯) Multi-Media Sampling	_3_hours (lays)
	( ) Decontamination	hours	days	( X ) Decontamination	3 (hours) days
3.	PHYSICAL HAZARDS TO P	ERSONNEL	·	· ·	
	· ·	,			
	(X) Heat ( ) Cold ( )	Precipitation	( ) (	Confined Space (X) Terrain	
	( <b>X</b> ) Walking/Working Surface	ces ( ) Fire	and Exp	olosion ( ) Oxygen Deficienc	y
	( ) Underground Utilities	( ) Overhead	l Utilitie	s (X) Heavy Equipment	
	(💢) Unknowns in Drums, Tar	nks, or other Co	ontainer	s ( ) Noise ( ) Ponds, La	goons or Impoundments
	(X) Rivers, Streams or Creeks	s ( ) Pressu	ırized C	ontainers or Systems	
	( ) Illumination ( ) Non	-Ionizing Radia	ation (	) Ionizing Radiation*	
	*Requires Health Physics Noti	fication / Supp	ort		
4.	BIOLOGICAL HAZARDS TO	) PERSONNEI			
	( ) Infectious or Medical Ho	enital Wasta	( ) No	on-Domesticated Animals (V)	Insects
	, .				
	(X) Poisonous Plants/ vegeta	mon ( ) Ka	W Sewa	ge .	
5	TRAINING REQUIREMENT	S			
	( V ) 40 Hour Congral Site W	orker Course w	ith three	-days supervised experience	
	( ) 24-Hour Course for limit	ited, specific tas	ks with	one day supervised experience.	
			ne day s	supervised experience.	
			ing.		
	( ) Site Specific Health and	Safety Training	g. Speci	fy:	<u> </u>
	( ) Pre-Entry training for e	mergency respo	nse skil	led support personnel.	
6.	MEDICAL SURVEILLANCE	REQUIREMEN	NTS	· · ·	·
	( X ) Baseline initial physical	examination w	/ physic	cian certification.	•
	(X) Annual physical examir	nation w / phys	ician ce	rtification.	
			ol (Rad	iation, Pesticide, PCB, Metals)	
	( ) Asbestos worker protoc	oi urveillance. Re	ason:		
	( ) Examination required in	n the event of cl	hemical	trauma or exposure.	
	•	Multi-Media Samplinghours days ( × ) Multi-Media Sampling3 hours days   Decontaminationhours days ( × ) Decontamination3 hours days   Decontaminationhours days ( × ) Decontamination3 hours days   Decontaminationhours days ( × ) Decontamination3 hours days   Decontamination			

7.

Physical	Chemical Contaminant		Chemical Contaminant		
Parameters		,	see ms	05 Atteched	
Chemical Name		. <b>4</b>	Lead		
Synonyms	Uhknow	ν ·	Craci		
Exposure Limits	OSHA	ACGIH	OSHA	ACGIH	
PEL/TLV	ppmmg/m³	ppmmg/m³	ppmmg/m³	ppmmg/m³	
STEL	ppmmg/m³	ppmmg/m³	ppmmg/m³	ppmmg/m <sup>3</sup>	
IDLH	ppmmg/m³	ppmmg/m³	ppmmg/m³	ppmmg/m³	
Ceiling	ppmmg/m³	ppmmg/m <sup>3</sup>	ppmmg/m³	ppmmg/m³	
Skin Absorber	Yes	No	Yes No		
Physical Form	SolidLiquidGas		Solid	=	
Color / Odor	Color:	Odor:	Color : (		
Flammability Data	Flash Point	°F or °C	Flash Point	•	
	LEL%	UEL%	. LEL%	UEL%	
Vapor Pressure		_mm/Hg		=	
Vapor Density		Air=1		Air=1	
Specific Gravity		_Water=1		_Water=1	
% Soluble in H2O	%	or Insoluble	%	or Insoluble	
- Incompatible	. Acids Bases Oxidizer	s Other:		s Other:	
Materials	Metals Water Alcohols Other:		Metals Water Alcohols Other:		
Routes of	Inhalation	Absorption	Inhalation	Absorption	
Exposure	Contact	Ingestion	ContactIngestion		
Symptoms of	Inhalation:		Inhalation:		
Acute Exposure	Absorption:		Absorption:		
	Ingestion:		Ingestion:		
,	Contact:	·	Contact:		
First Aid	Eye Contact: Irrigate Immediat	ely	Eye Contact: Irrigate Immediat	ely	
Treatment	Skin Contact: Wash with Soap	and Water	Skin Contact: Wash with Soap	and Water	
	Breathing: Respiratory Suppor	<b>t</b> '	Breathing: Respiratory Support		
	If Swallowed: Seek Immediate	Medical Attention	If Swallowed: Seek Immediate Medical Attention		
Ion Potential		eV	eV		
Instruments for	PID w/	eV probeFID	PID w/6	V probeFID	
Detection	CGIColorin	netric TubeMonitox	CGIColorim	etric TubeMonitox	
	Jerome (Hg)	_Jerome (H2S)pH		pHpH	
·	Other:		Other:		
Sampling Method	NIOSH Method	#	NIOSH Method #		
NIOSH	OSHA Method	#	OSHA Method #		
OSHA	EPA Method #	·	EPA Method #	<del></del>	
EPA			·		
Į.		•			
	·				

Physical	Chemical C	Contaminant	Chemical Contaminant		
Parameters				-No.	
Chemical Name					
Synonyms					
Exposure Limits	OSHA	ACGIH	OSHA	ACGIH	
PEL/TLV	ppmmg/m³	ppmmg/m³	ppmmg/m³	ppmmg/m³	
STEL	ppmmg/m³	ppmmg/m³	ppmmg/m³	ppmmg/m³	
IDLH	ppmmg/m³	ppmmg/m³	ppmmg/m³	ppmmg/m³	
Ceiling	ppmmg/m³	ppmmg/m³	ppmmg/m³	ppmmg/m³	
Skin Absorber	Yes	No	Yes I	No	
Physical Form	°Solid	_LiquidGas	SolidLi	•	
Color / Odor	Color:	Odor:	Color : Od		
Flammability Data	Flash Point	°F or °C	Flash Point	•	
	%	UEL%	LEL% (	<del></del>	
Vapor Pressure		_mm/Hg		, 0	
Vapor Density		Air=1			
Specific Gravity		_Water=1		Water=1	
% Soluble in H <sub>2</sub> O	%	or Insoluble		or Insoluble	
Incompatible Materials	Acids Bases Oxidizer  Metals Water Alcohols		Acids Bases Oxidizers Metals Water Alcohols	Other:	
Routes of		Absorption	Inhalation _	Absorption	
Exposure	Contact	Ingestion	Contact _	Ingestion	
Symptoms of	Irihalation:		Inhalation:		
Acute Exposure	Absorption:		Absorption:	<u> </u>	
. 32	Ingestion:		Ingestion:		
	Contact:		Contact:		
First Aid	Eye Contact: Irrigate Immediate	ely	Eye Contact: Irrigate Immediately	<b>y</b> _	
Treatment	Skin Contact: Wash with Soap a	and Water	Skin Contact: Wash with Soap an	d Water	
	Breathing: Respiratory Support	t	Breathing: Respiratory Support	1	
	If Swallowed: Seek Immediate		If Swallowed: Seek Immediate M		
Ion Potential		eV		eV	
Instruments for	PID w/e	eV probeFID	PID w/eV	probeFID	
Detection	i	netric TubeMonitox	CGIColorimet	ric TubeMonitox	
	Jerome (Hg) Other:	pH	Jerome (Hg)J	erome (H <sub>2</sub> S)pH	
Sampling Method			,	. <del></del>	
NIOSH	NIOSH Method	<del></del>	NIOSH Method #_	· 	
OSHA	OSHA Method #		OSHA Method #_	12_0 2	
EPA	EPA Method #_		EPA Method #		

Physical	ysical Chemical Contaminant		Chemical Contaminant				
Parameters							· •
Chemical Name							
Synonyms					·		
Exposure Limits	OSHA	ACGIH		OSHA	1	ACGI	Н
PEL/TLV	ppmmg/m³	ppmn	ng/m³	ppm	mg/m³	ppm _	mg/m³
STEL	ppmmg/m³	ppmn	ng/m³	ppm	mg/m³	ppm _	mg/m³
IDLH	ppmmg/m³	ppmn	ng/m³	ppm	mg/m³	ppm _	mg/m³
Ceiling	ppmmg/m³	рртп	ng/m³	ppm	mg/m³	ppm _	mg/m³
Skin Absorber	Yes No			Yes	No		
Physical Form	Solid	SolidLiquidGas				iquidGas	
Color / Odor	Color:	Odor:		Color :	0	lor:	
Flammability Data	Flash Point	°F or °C			sh Point		
	LEL%	UEL%		I	.EL% (	JEL%	
Vapor Pressure		_mm/Hg					
Vapor Density		Air=1				_Air=1 	·
Specific Gravity		_Water=1				Water=1	
% Soluble in H <sub>2</sub> O	%	or Insoluble			% o	r Insoluble	
Incompatible	Acids Bases Oxidizer	s Other:		Acids Base		Other:	
Materials	Metals Water Alcohols	Other:		Metals Wate	er Alcohols (	Other:	
Routes of	Inhalation	Absorption			_Inhalation _	Absorption	
Exposure	Contact	Ingestion			Contact _	Ingestion	
Symptoms of	Inhalation:			Inhalation:			
Acute Exposure	Absorption:			Absorption:	<del></del> .		•
	Ingestion:	<del></del>		Ingestion:			
	Contact:			Contact:			
First Aid	Eye Contact: Irrigate Immediate	ely		Eye Contact: Irriga	•		
Treatment	Skin Contact: Wash with Soap a	and Water	-	Skin Contact: Was	_		· ·
	Breathing: Respiratory Support			Breathing: Respiratory Support			
	If Swallowed: Seek Immediate	Medical Attention	_	If Swallowed: See	k Immediate M	edical Attention	<del></del>
Ion Potential	·	eV				eV	
Instruments for	PID w/e	V probeFID		P	ID w/eV	probeFIL	)
Detection	CGIColorim	etric TubeMonit	ox	CGI _	Colorimet	ric TubeN	<b>fonitox</b>
		Jerome (H <sub>2</sub> S)p	Н		(Hg)J	erome (H <sub>2</sub> S)	pH
·	Other:			Other:	- <del></del>		<del></del>
Sampling Method					CITA-1 12		
NIOSH		<u> </u>				•	
OSHA		·				···	
EPA	EPA Method #_	·		, EP	A Method #		

DECONTAMINATION PROCEDURES	
( ) Wet Decontamination (circle as appropriate):	Water DI Water Distilled Water Alconox Hexane Acetone Nitric Acid Methanol Soap
	Other:
W D D	
Description of Site Specific Decontamination Plan:	Disposable Sampling Equipment
Description of Site Specific Decontamination Plan:	Disposable Sampling equipment  orguipment items will be place  long with used pp= and do
	Disposable Sampling equipment  equipment items will be place  long with Used PPE and do
Description of Site Specific Decontamination Plan:	

Adequacy of decontamination determined by: Visual Observation Grab Sample

Rinsate Blank Wipe Sample

## 9. EMERGENCY TELEPHONE NUMBERS

Emergency Contact	Location	Telephone Number	Notified
Hospital (Primary)  Sol ω. 14 <sup>Th</sup> St.	medical Center of Delaware	302-428- 4886	Yes (Vo
Hospital (Secondary)	:		Yes No
Ambulance	Wilmington	911	Yes No
Police	Wilmington 12th street	911	Yes No
Fire Department	wilming ten	911	Yes No

Does Primary Hospital have chemical trauma capability? Yes No
If no, then what is closest back-up? Telephone Number:
Directions to Hospital (attach map) - Route verified by: on on
bridge for creek, turn right onto Rte 52 (10th St.), Men
right onto worth washington street, lett onto 14th
Street. Hospital 15 on the right. (2-miles from site)  [501 west 14th street]
Tsol west 14th street



Contact	Telephone Number
On-Call Mobile Telephone	609-304-3616
Back-Up Telephone	609-304-3617
Team Leader Pager	888-519-5074
Safety Officer Pager	888-519-5084
Equipment Pager	888-519-5087
Weston Emergency Medical Consultant	800-229-3674
Continuum Healthcare	
OHM Emergency Medical Consultants	757-466-5999
NDC	757-466-5818
National Poison Control Center	800-942-5969
CHEMTREC (Emergency)	800-424-9300
CHEMTREC (Non-emergency)	800-262-8200
ATSDR	404-639-0615
ATF (Explosives Information)	800-424-9555
National Response Center	800-424-8802
Regional Response Center	215-814-9016
Utility Markout Services	
Pennsylvania	800-242-1776
Delaware	800-282-8555
Maryland	800-257-7777
Virginia	800-552-7001
West Virginia	800-245-4848
District of Columbia	800-257-7777

Carried States

Task to be Performed	Anticipated	Type of Chemical	Inner Glove	Type of APR Cartridge
Air Monitoring / Sampling Required	Level of Protection	Protective Coverall	Outer Glove	(MSA)
Frequency and Type of Air Monitoring		,	Boot Cover	
Task #1	Level A	MSA Chempruf II	Nitrile Surgical	GME-H
Site Recon Drum Sampling HazCat Air Sampling	SCBA	(BETEX)	Silver Shield	P100/OV/CLHC/SD/AM/MA/
)	or	MSA Chempruf II		CD/HS/FM/HF
Soil Sampling Mag Survey Sediment Sampling	ŀ			
Grid-Layout Site Survey Soil Gas Survey	Airline	(VAUTEX)	Nitrile Butyl	GMI-P100
GW Sampling PRP Monitoring Direct Push Sampling		Trelleborg Trellchem HPS	PVA Viton PVC	
Other:	Level B	Other:	Rubber Neoprene	P100/OV/I
	SCBA		Leather Work Gloves	
, FID PID CGI 260 CGI 360 CGI 361 μR Meter	or	Barricade Chemrel	Jersey Gloves	Mersorb-P100
Cannonbail II Monitox: G-M Meter	Airline	Responder Saranex	Other:	P100/CL/MV
Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube		Tyvek Nomex		
Detector Tube: RAM DataRam Füter	Level C	Butyl Spiash Apron	Latex Neoprene	P100-HEPA OV-Organic Vapor
	APR	Cotton Coveralls	Nitrile Steel Toe	CL-Chlorine SD-Sulfur Dioxide
Continuous	or	Work Uniform	Other:	CD-Chlorine Dioxide
Periodic: Every 30 mir(s) hour(s)	PAPR	Other:		AM-Ammonia
renous: every	'5''		•	FM-Formaldehyde
A sales t soute		1		MA-Methylamine I-lodine
Action Levels  Organic Vapors:ppm Particulate:pmg/m³	Level D			HS-Hydrogen Sulfide (Escape)
				MV-Mercury Vapor
Unknown Organic - 0→5 ppm, don "Level C" protection	j			HC-Hydrogen Chloride
5→500 ppm, don "Level B" protection	1			HF-Hydrogen Flouride
LEL: > 10% (Confined Space) >20% Ambient Air	<b>j</b>			
O <sub>2</sub> : <19.5% >23.5%				
Radiation: 3 x bkg or 1mR/hr - leave area				
Task # 2	Level A	MSA Chempruf II	Nitrile Surgical	GME-H
Site Recon Drum Sampling HazCat Air Sampling	SCBA	(BETEX)	Silver Shield	P100/OV/CLHC/SD/AM/MA/
Soil Sampling Mag Survey Sediment Sampling	, or	MSA Chempruf II		CD/HS/FM/HF
Grid Layout Site Survey Soil Gas Survey	Airline	(VAUTEX)	Nitrile Butyl	
GW Sampling PRP Monitoring Direct Push Sampling		Trelleborg Trellchem HPS	PVA Viton PVC	GMI-P100
Other Vegetation Clearing	Level B	Other:	Rubber Neoprene	P100/OV/I
A Spotter will be used 30	SCBA		Ceather Work Gloves	
FID PID CGI 260 CGI 360 CGI 361 µR Meter	or	Barricade Chemrel	Jersey Gloves	Mersorb-P100
Cannonball II Monitox: G-M Meter	Airline	Responder Saranex	Other:	P100/CL/MV
	11416	Tyvek Nomex		
Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube		Butyl Splash Apron		P100-HEPA OV-Organic Vapor
Detector Tube: RAM DataRam Filter	Level C	Cotton Coveralls	Latex Neoprene	CL-Chlorine SD-Sulfur Dioxide
	APR	Work Uniform	Nitrile Steel Toe	CD-Chlorine Dioxide
Continuous	or	·	Other:	AM-Ammonia
Periodic: Every 30 hings) hour(s)	PAPR	Other: ¶		
				FM-Formaldehyde
Action Levels	Level D			MA-Methylamine I-lodine
Organic Vapors:ppm Particulate: DV mg/m³				HS-Hydrogen Sulfide (Escape)
Unknown Organic - 0→5 ppm. don "Level C" protection		,		MV-Mercury Vapor
	1		1	HC-Hydrogen Chloride
5→500 ppm, don "Level B" protection	1		l .	HF-Hydrogen Flouride
'				i i i i i i i i i i i i i i i i i i i
LEL: > 10% (Confined Space) > 20% Ambient Air			-	rir-riyutogen riomiae
LEL: > 10% (Confined Space) > 20% Ambient Air O <sub>2</sub> : <19.5% > 23.5%			-	ru-riyanogen ribanae
LEL: > 10% (Confined Space) > 20% Ambient Air			-	ri-riyatoger rounae

			T	1
Task to be Performed	Anticipated Level of	Type of Chemical Protective Coverall	Inner Glove	Type of APR Cartridge
Air Monitoring / Sampling Required	Protection		Outer Glove	(MSA)
Frequency and Type of Air Monitoring			Boot Cover	
Task #3	Level A	MSA Chempruf II	Nitrile Surgical	GME-H
Site Recon Orum Sampling HazCat Air Sampling	SCBA	(BETEX)	Silver Shield	P100/OV/CLHC/SD/AM/MA/
Soil Sampling Mag Survey Sediment Sampling	or ·	MSA Chempruf II		CD/HS/FM/HF
Grid Layout Site Survey Soil Gas Survey	Airline	(VAUTEX)	Nitrile Butyl	
GW Sampling PRP Monitoring Direct Push Sampling		Treileborg Trellchem HPS	PVA Viton PVC	GMI-P100
Other:	Level B	Other:	Rubber Neoprene	P100/OV/I
	SCBA		Leather Work Gloves	
FID (PID) CGI 260 CGI 360 CGI 361 (FR Meter)	or	Barricade Chemrel	Jersey Gloves	Mersorb-P100
	Airline	Responder (Saranex	Other:	PI00/CL/MV
	Allile	Tyvek Nomex	, Julius	
Jerome Meter (H₂S) Jerome Meter (Hg) Sorbent Tube		Butyl Splash Apron		P100-HEPA OV-Organic Vapor
Detector Tube: RAM DataRam Filter	Level C	Cotton Coveralls	(Latex) Neoprene	CL-Chlorine SD-Sulfur Dioxide
	APR	Work Uniform	Nitrile Steel Toe	CD-Chlorine Dioxide
Continuous	or '	•	Other:	AM-Ammonia
Periodic: Every (s) hour(s)	PAPR ·	Other:		FM-Formaldehyde
				MA-Methylamine I-lodine
Action Levels	Level D			
Organic Vapors:ppm Particulate:mg/m³				HS-Hydrogen Sulfide (Escape)
Unknown Organic - 0→5 ppm, don "Level C" protection				MV-Mercury Vapor
5->500 ppm, don "Level B" protection	٠			HC-Hydrogen Chloride
LEL: > 10% (Confined Space) > 20% Ambient Air				HF-Hydrogen Flouride
O <sub>2</sub> : <19.5% >23.5%			,	
Radiation: 3 x bkg or 1mR/hr - leave area		٠.		
Task # 4	Level A	MSA Chempruf II	Nitrile Surgical	GME-H
Site Recon Drum Sampling HazCat Air Sampling	SCBA	(BETEX)	Silver Shield	P100/OV/CLHC/SD/AM/MA/
Soil Sampling Mag Survey Sediment Sampling	or	MSA Chempruf II		CD/HS/FM/HF
Grid Layout Site Survey Soil Gas Survey	Airline	(VAUTEX)	Nitrile Butyl	
GW Sampling PRP Monitoring Direct Push Sampling		Trelleborg Trellchem HPS	PVA Viton PVC	GMI-P100
Other Ash-like material Samplishy	Lavel B	Other:	Rubber Neoprene	P100/OV/I
7 7	Level B SCBA		Leather Work Gloves	
THE COURSE COURSE COURSE	5.DA		L CHICAL TOUR CHOICE	1
FID (PID) CGI 260 CGI 360 CGI 361 (µR Meter)		Barrierda Charrel	lareau Cloure	Mersorb-P100
	Of Ai-line	Barricade Chemrel	Jersey Gloves	Mersorb-P100 P100/CL/MV
Cannonball II Monitox: G-M Meter	or Airline	Responder Saranex	Jersey Gloves Other:	
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube		Responder Saranex  Tyvek Nomex	Other:	P100/CL/MV
Cannonball II Monitox: G-M Meter	Airline Level C	Responder Saranex Tyvek Nomex Butyl Splash Apron	Other:Neoprene	P100/CL/MV P100-HEPA OV-Organic Vapor
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube	Airline	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor **  CL-Chlorine SD-Sulfur Dioxide
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube	Airline Level C	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls Work Uniform	Other:Neoprene	P100/CL/MV  P100-HEPA OV-Organic Vapor  CL-Chlorine SD-Sulfur Dioxide  CD-Chlorine Dioxide
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube  Detector Tube: RAM DataRam Filter	Airline  Level C  APR	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor **  CL-Chlorine SD-Sulfur Dioxide  CD-Chlorine Dioxide  AM-Ammonia
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube  Detector Tube: RAM DataRam Filter  Continuous	Airline  Level C  APR  or	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls Work Uniform	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor CL-Chlorine SD-Sulfur Dioxide CD-Chlorine Dioxide AM-Ammonia FM-Formaldehyde
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube  Detector Tube: RAM DataRam Filter  Continuous  Periodic: Every min/\$ hour(\$)	Airline  Level C  APR  or	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls Work Uniform	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor **  CL-Chlorine SD-Sulfur Dioxide  CD-Chlorine Dioxide  AM-Ammonia  FM-Formaldehyde  MA-Methylamine 1-lodine
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube  Detector Tube: RAM DataRam Filter  Continuous  Periodic: Everymin(s) hour(s)	Airline  Level C  APR  or  PAPR	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls Work Uniform	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor ** CL-Chlorine SD-Sulfur Dioxide CD-Chlorine Dioxide AM-Ammonia FM-Formaldehyde MA-Methylamine I-lodine HS-Hydrogen Sulfide (Escape)
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube  Detector Tube: RAM DataRam Filter  Continuous  Periodic: Every min/\$ hour(\$)	Airline  Level C  APR  or  PAPR	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls Work Uniform	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor ** CL-Chlorine SD-Sulfur Dioxide CD-Chlorine Dioxide AM-Ammonia FM-Formaldehyde MA-Methylamine I-lodine HS-Hydrogen Sulfide (Escape) MV-Mercury Vapor
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube  Detector Tube: RAM DataRam Filter  Continuous  Periodic: Every min/s) hour(s)  Action Levels  Organic Vapors: ppm Particulate: D_N mg/m³	Airline  Level C  APR  or  PAPR	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls Work Uniform	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor CL-Chlorine SD-Sulfur Dioxide CD-Chlorine Dioxide AM-Ammonia FM-Formaldehyde MA-Methylamine I-lodine HS-Hydrogen Sulfide (Escape) MV-Mercury Vapor HC-Hydrogen Chloride
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube  Detector Tube: RAM DataRam Filter  Continuous  Periodic: Everymin/s) hour(s)  Action Levels  Organic Vapors: ppm Particulate: mg/m³  Unknown Organic - 0→5 ppm, don "Level C" protection	Airline  Level C  APR  or  PAPR	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls Work Uniform	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor CL-Chlorine SD-Sulfur Dioxide CD-Chlorine Dioxide AM-Ammonia FM-Formaldehyde MA-Methylamine I-lodine HS-Hydrogen Sulfide (Escape) MV-Mercury Vapor
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube  Detector Tube: RAM DataRam Filter  Continuous  Periodic: Every mink) hour(s)  Action Levels  Organic Vapors: ppm Particulate: mg/m³  Unknown Organic - 0-35 ppm, don "Level C" protection  5-500 ppm, don "Level B" protection	Airline  Level C  APR  or  PAPR	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls Work Uniform	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor CL-Chlorine SD-Sulfur Dioxide CD-Chlorine Dioxide AM-Ammonia FM-Formaldehyde MA-Methylamine I-lodine HS-Hydrogen Sulfide (Escape) MV-Mercury Vapor HC-Hydrogen Chloride
Cannonball II Monitox: G-M Meter  Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube  Detector Tube: RAM DataRam Filter  Continuous  Periodic: Every min/s) hour(s)  Action Levels  Organic Vapors: ppm Particulate: D_1 mg/m³  Unknown Organic - 0→5 ppm, don "Level C" protection  5→500 ppm, don "Level 8" protection  LEL: > 10% (Confined Space) > 20% Ambient Air	Airline  Level C  APR  or  PAPR	Responder Saranex Tyvek Nomex Butyl Splash Apron Cotton Coveralls Work Uniform	Other:  Catex Neoprene  Nitrile Steel Toe	P100/CL/MV  P100-HEPA OV-Organic Vapor CL-Chlorine SD-Sulfur Dioxide CD-Chlorine Dioxide AM-Ammonia FM-Formaldehyde MA-Methylamine I-lodine HS-Hydrogen Sulfide (Escape) MV-Mercury Vapor HC-Hydrogen Chloride

Task to be Performed	Anticipated Level of	Type of Chemical Protective Coverall	Inner Glove	Type of APR Cartridge
Air Monitoring / Sampling Required	Protection	f .	Outer Glove	(MSA)
Frequency and Type of Air Monitoring		, 	Boot Cover	
Task #5	Level A	MSA Chempruf II	Nitrile Surgical	GME-H
Site Recon Drum Sampling HazCat Air Sampling	SCBA	(BETEX)	Silver Shield	P100/OV/CLHC/SD/AM/MA/ .
Soil Sampling Mag Survey Sediment Sampling	or	MSA Chempruf II		CD/HS/FM/HF
Grid Layout Site Survey Soil Gas Survey	Airline	(VAUTEX)	Nitrile Butyl	
GW Sampling PRP Monitoring Direct Push Sampling		Trelleborg Trellchem HPS	PVA Viton PVC	GMI-P100
Other:		Other:		P100/OV/I
	Level B	•	Rubber Neoprene	
	SCBA		Leather Work Gloves	Mersorb-P100
FID (PID) CGI 260 CGI 360 CGI 361 (µR Meter)	or	Barricade Chemrel	Jersey Gloves	P100/CL/MV
Cannonball II Monitox: G-M Meter	Airline	Responder Saranex .	Other:	, 135, 42, 111
Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube		Tyvek Nomex		
Detector Tube: RAM DataRam Filter	Level C	Butyl Splash Apron	(Latex) Neoprene	P100-HEPA OV-Organic Vapor
	APR	Cotton Coveralls	Nitrile Steel Too	CL-Chlorine SD-Sulfur Dioxide
Continuous	, or	Work Uniform	Other:	CD-Chlorine Dioxide
. Periodic: Every min(s) hour(s)	PAPR	Other:		AM-Ammonia
				FM-Formaldehyde
Action Levels	(Level D)			MA-Methylamine I-lodine
Organic Vapors:ppm Particulate: D\X mg/m³				HS-Hvdrogen Sulfide (Escape)
Unknown Organic - 0→5 ppm, don "Level C" protection "				MV-Mercury Vapor
5→500 ppm, don "Level B" protection				HC-Hydrogen Chloride
LEL: > 10% (Confined Space) > 20% Ambient Air			· .	HF-Hydrogen Flouride
Oz: <19.5% >23.5%			•	
Radiation: 3 x bkg or 1mR/hr - leave area				
	Level A	MSA Chempruf II	Nitrile Surgical	GME-H
Task # 6	SCBA	·	Silver Shield	P100/OV/CLHC/SD/AM/MA/
Site Recon Drum Sampling HazCat Air Sampling		(BETEX)  MSA Chempruf II	Saver Sidela	CD/HS/FM/HF
Soil Sampling Mag Survey Sediment Sampling	or			
Grid Layout Site Survey Soil Gas Survey	Airline	(VAUTEX)	Nitrile Butyl	GMI-P100
GW Sampling PRP Monitoring Direct Push Sampling		Trelleborg Trellchem HPS	PVA Viton PVC	P100/OV/I
Other:	Level B	Other:	Rubber Neoprene	P100/04/1
	5CBA		Leather Work Gloves	
FID (PID) CGI 260 CGI 360 CGI 361 µR Meter	or .	Barricade Chemrel	Jersey Gloves	Mersorb-P100
Cannonball II Monitox: G-M Meter	Airline	Responder Saranex	Other:	P100/CL/MV
Jerome Meter (H <sub>2</sub> S) Jerome Meter (Hg) Sorbent Tube		Tyvek Nomex		
Detector Tube: RAM DataRam Filter	Level C	Butyl Splash Apron	(Latex) Neoprene	P100-HEPA OV-Organic Vapor
, "	APR	Cotton Coveralls	Nitrile (Steel Toe	CL-Chlorine SD-Sulfur Dioxide
Continuous	or	. Work Uniform	Other:	CD-Chlorine Dioxide
Periodic: Every min(s) hour(s)	PAPR	Other:		AM-Ammonia
remodic: Every muita) mourta)		,		FM-Formaldehyde
A satura P consta				MA-Methylamine I-lodine
Action Levels	Tevel D			HS-Hydrogen Sulfide (Escape)
Organic Vapors:ppm Particulate:mg/m³				MV-Mercury Vapor
Unknown Organic - 0→5 ppm, don "Level C" protection				HC-Hydrogen Chloride
5→500 ppm, don "Level B" protection	1	•		HF-Hydrogen Flouride
LEL: > 10% (Confined Space) >20% Ambient Air	'			1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
O <sub>2</sub> : <19.5% >23.5%	,			'
Radiation: 3 x bkg or ImR/hr - leave area				-

4	(D) (4)	
HASP prepared by: Pre-Review and Approv		Date: 8-17-99 Date: 8/24/59
Modification to original	•	Date:
Review and Approval b	y RSO:	Date:
Health Physicist Approv	val (if required):	Date:
	· ·	

ORIGINAL

# $\uparrow$ COMPLETE PRIOR TO SITE ACTIVITIES $\uparrow$

## 12. DIRECT READING INSTRUMENT CALIBRATION DATA

13.

Direct Reading Instrument	Combustible Gas Indicator O <sub>2</sub> Meter	Radiation Survey Meter	P.I.D.	F.I.D.	Colorimetric Tube
Instrument or Tube Type	MSA Model 260 MSA Model 360 MSA Model 361 Cannonball II	Geiger-Mueller MicroR	hNU MicroTip	OVA	
Decal Number	-			·	
Calibration Date					
SATA Member	,				
Cal Check by RSO	Ý			. !	

PHISICAL DESCRIPTION OF SITE AND RESPONSE ACTIVITIES	
Size of Site: 20 acres square feet square miles	
Weather: Cloud Cover - 1/4 1/2 3/4 Overcast Humidity: Low Medium High	
Temp:°F or °C Windsmph from N NE E SE S SW W N	W
Nearest Waterway: Brandywink Cr. Distance from Site: 10 (feet) miles	
Distance to nearest: Residence: feet miles School: feet miles	
Hospital: feet miles Public Building: 700 (feet) miles	
Actions taken on site: Perimeter Monitoring? Yes No	
Site Entry by SATA? Yes No	

ON RIAN

Tasks Conducted	Level of Protection / Specific PPE Used
Task #1	As specified in Section 11
	If other:
	Coverall: Shoe Covers:
	In Gloves:Out Gloves:
	Respirator:*
Task #2	As specified in Section 11
	If other:
·	Coverall: Shoe Covers:
·	In Gloves:Out Gloves:
	Respirator:*
Task #3	As specified in Section 11
	If other:
	Coverall: Shoe Covers:
	In Gloves: Out Gloves:
	Respirator:*
Task #4	As specified in Section 11
	If other:
	Coverall: Shoe Covers:
	In Gloves:Out Gloves:
	Respirator:*
Task #5	As specified in Section 11
	If other:
	Coverall: Shoe Covers:
•	In Gloves: Out Gloves:
	Respirator:*
Task #6	As specified in Section 11
	If other:
	Coverall: Shoe Covers:
·	Inn Gloves: Out Gloves:
	Respirator:*

<sup>\*</sup> Change in level of respiratory protection requires RSO approval.

15.

OPIGNAL

	,					(b) (4)	
Date:	У	/	31	, 99	Collected by:		

Station	CGI/O₂ Meter	Radiation	PID	FID	Jerome Meter	RAM	Colorimetric Tube
Location	Cannonball II	Meter			Mercury	or	
, t					or	PdRAM	
		,			H₂S	*	·
Background	%LEL	μR/hr				6 nelhr	ppm
Readings	%O <sub>2</sub>	mR/hr	units	units	mg/m³ Hg	µg/m³	ppm
	ppm CO	CPM				or	ppm
	ppm H <sub>2</sub> S				ppm H <sub>2</sub> S	mg/m³	ppm
	%LEL	μR/h <b>r</b>			.,		ppm
T5-	%O <sub>2</sub>	mR/hr	2000 units	units	mg/m³ Hg	μg/m³	ppm
DC	CO		ppM			or	ppm
(0120 (00 test)	ppm H₂S				ppm H <sub>2</sub> S	mg/m³	ppm
(0)	%LEL	μR/hr					ppm
	%O <sub>2</sub>	mR/hr	units	units	mg/m³ Hg	µg/m³	ppm
	ppm CO	СРМ				or	ppm
	ppm H <sub>2</sub> S				′ppm H₂S	mg/m³	ppm
	%LEL	μR/hr					ppm
	%O <sub>2</sub>	mR/hr	units	units	mg/m³ Hg	µg/m³	ppm
	ppm CO	СРМ				or	ppm
G.	ppm H <sub>2</sub> S			,	ppm H₂S	mg/m³	ppm
	%LEL	μR/hr		_			ppm
	%O <sub>2</sub>	mR/hr	units	units	mg/m³ Hg	μg/m³	ppm
	ppm CO	СРМ				or	ppm
	ppm H <sub>2</sub> S		·		ppm H <sub>2</sub> S	mg/m³	ppm
	%LEL	μR/hr			<del></del>	-	ppm
	%O <sub>2</sub>	mR/hr	units	units	mg/m³ Hg	µg/m³	ppm
	ppm CO	СРМ		,	,	or	ppm
	ppm H <sub>2</sub> S				ppm H₂S	mg/m³	ppm
	%LEL	μR/hr					ppm
	%O <sub>2</sub>	mR/hr	units	units	mg/m³ Hg	µg/m³	ppm
	ppm CO	СРМ				or	ppm
	ppm H <sub>2</sub> S				ppm H₂S	mg/m³	ppm
		L	<u> </u>				<u> </u>

## 17. HAZARDOUS WASTE SITE AND ENVIRONMENTAL SAMPLING ACTIVITIES

Were samples obtained :	Off Site	Yes	No
	On Site	Yes	No

Type of Samples (Circle all that apply): Air Surface Water Found Water Drum/ Tank

Soil Sediment Asbestos Biological Other: Ash-like material

How obtained (circle all that apply): Scoop Drum Thief / Coliwasa SS Trowel

Split Spoon Auger Bailer Dredge Bottle Immersion Pump

Was Lab Notified of Potential Hazard Level of Samples?

Other:\_

18.

Name (Printed)	Signature	Affiliation	Date
(b) (4)			8/26/99
-			8/23/99
-			8-26-8
- -			8-26-9
			8/3//99
			9/29/00
			,

Disclaimer: This Health and Safety Plan (HASP) was prepared for work to be conducted under the Site Assessment Technical Assistance (SATA) Contract 68-S5-3002. Use of this HASP by WESTON and its subcontractors is intended to fulfill the OSHA requirements found in 29 CFR 1910.120. Items not specifically covered in this HASP are included by reference to 29 CFR 1910 and 1926.

	Signature	Date
Final Submission of HASP by:		÷ .
Does Plan Preparer Need Copy?	Yes No	
Post Response Review by:		9/20/9
Post Response Approval by:		

	Comments / Follow Up					
NO Sik	clockin	mp.				
	•					
· 						•
	· · · · · · · · · · · · · · · · · · ·					

Please reduce your browser font size for better viewing and printing



## Material Safety Data Sheet

From: Mallinekrodt Baker, Inc. 222 Red School Lane Phillipsburg, NJ 08865





24 Hour Emergency Telephone: 908-859-2151 CHEMTREC: 1-800-424-9300

National Response in Canada CANUTEC: 613-896-6668

Outside U.S. and Canada Chemtree: 202-483-7616

NOTE: CREMITIES, CANVITES and Resignal Resignate Conter emergency numbers to be used only in the event of chemical amergencies swelving a spit, leak, lire, expects or accident smolving chemicals.

All non-emergency questions should be directed to Customer Service (1-800-582-2537) for assistance.

## LEAD METAL

MSDS Number: L2347 --- Effective Date: 12/08/96

## 1. Product Identification

Synonyms: Granular lead, pigment metal; C.I. 77575

CAS No.: 7439-92-1

Molecular Weight: 207.19 Chemical Formula: Pb

Product Codes: J.T. Baker: 2256, 2266 Mallinckrodt: 5668

# 2. Composition/Information on Ingredients

Ingredient	CAS No	Percent	Hazardous
Lead	7439-92-1	95 - 100%	Yes

## 3. Hazards Identification

Emergency Overview

POISON! DANGER! MAY BE FATAL IF SWALLOWED OR INHALED. CAUSES IRRITATION TO SKIN, EYES AND RESPIRATORY TRACT. NEUROTOXIN. AFFECTS THE GUM TISSUE, CENTRAL NERVOUS SYSTEM, KIDNEYS, BLOOD AND REPRODUCTIVE SYSTEM. POSSIBLE CANCER HAZARD. MAY CAUSE CANCER BASED ON ANIMAL DATA. Risk of cancer depends on duration and level of exposure.

## J.T. Baker SAF-T-DATA<sup>(tm)</sup> Ratings (Provided here for your convenience)

Health Rating: 3 - Severe (Life) Flammability Rating: 0 - None Reactivity Rating: 0 - None Contact Rating: 1 - Slight

Lab Protective Equip: GOGGLES, LAB COAT, VENT HOOD, PROPER GLOVES

Storage Color Code: Blue (Health)

#### Potential Health Effects

#### Inhalation:

Lead can be absorbed through the respiratory system. Local irritation of bronchia and lungs can occur and, in cases of acute exposure, symptoms such as metallic taste, chest and abdominal pain, and increased lead blood levels may follow. See also Ingestion.

#### Ingestion:

POISON! The symptoms of lead poisoning include abdominal pain and spasms, nausea, vomiting, headache. Acute poisoning can lead to muscle weakness, "lead line" on the gums, metallic taste, definite loss of appetite, insomnia, dizziness, high lead levels in blood and urine with shock, coma and death in extreme cases.

#### Skin Contact:

Lead and lead compounds may be absorbed through the skin on prolonged exposure; the symptoms of lead poisoning described for ingestion exposure may occur. Contact over short periods may cause local irritation, redness and pain.

#### **Eye Contact:**


Absorption can occur through eye tissues but the more common hazards are local irritation or abrasion.

#### Chronic Exposure:

Lead is a cumulative poison and exposure even to small amounts can raise the body's content to toxic levels. The symptoms of chronic exposure are like those of ingestion poisoning; restlessness, irritability, visual disturbances, hypertension and gray facial color may also be noted.

#### Aggravation of Pre-existing Conditions:

Persons with pre-existing kidney, nerve or circulatory disorders or with skin or eye problems may be more susceptible to the effects of this substance.



## 4. First Aid Measures

#### Inhalation:

Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Get medical attention.

#### Ingestion:

Induce vomiting immediately as directed by medical personnel. Never give anything by mouth to an unconscious person. Get medical attention.

#### Skin Contact:

Immediately flush skin with plenty of soap and water for at least 15 minutes. Remove contaminated clothing and shoes. Get medical attention. Wash clothing before reuse. Thoroughly clean shoes before reuse.

#### Eye Contact:

Immediately flush eyes with plenty of water for at least 15 minutes, lifting lower and upper eyelids occasionally. Get medical attention immediately.

# 5. Fire Fighting Measures

#### Fire:

Not considered to be a fire hazard. Powder/dust is flammable when heated or exposed to flame.

#### **Explosion:**

Not considered to be an explosion hazard.

#### Fire Extinguishing Media:

Use any means suitable for extinguishing surrounding fire. Do not allow water runoff to enter sewers or waterways.

#### **Special Information:**

In the event of a fire, wear full protective clothing and NIOSH-approved self-contained breathing apparatus with full facepiece operated in the pressure demand or other positive pressure mode. Can produce toxic lead fumes at elevated temperatures and also react with oxidizing materials.

# 6. Accidental Release Measures

Ventilate area of leak or spill. Wear appropriate personal protective equipment as specified in Section 8. Spills: Sweep up and containerize for reclamation or disposal. Vacuuming or wet sweeping may be used to avoid dust dispersal. US Regulations (CERCLA) require reporting spills and releases to soil, water and air in excess of reportable quantities. The toll free number for the US Coast Guard National Response



# 7. Handling and Storage

Keep in a tightly closed container, stored in a cool, dry, ventilated area. Protect against physical damage. Isolate from incompatible substances. Areas in which exposure to lead metal or lead compounds may occur should be identified by signs or appropriate means, and access to the area should be limited to authorized persons. Containers of this material may be hazardous when empty since they retain product residues (dust, solids); observe all warnings and precautions listed for the product.

# 8. Exposure Controls/Personal Protection

#### **Airborne Exposure Limits:**

For lead, metal and inorganic dusts and fumes, as Pb: -OSHA Permissible Exposure Limit (PEL): 0.05 mg/m3 (TWA) For lead, elemental and inorganic compounds, as Pb: -ACGIH Threshold Limit Value (TLV): 0.05 mg/m3 (TWA), A3 animal carcinogen ACGIH Biological Exposure Indices (BEI): 30 ug/100ml, notation B (see actual Indices for more information). For lead, inorganic: -NIOSH Recommended Exposure Limit (REL): 0.1 mg/m3 (TWA)

## **Ventilation System:**

A system of local and/or general exhaust is recommended to keep employee exposures below the Airborne Exposure Limits. Local exhaust ventilation is generally preferred because it can control the emissions of the contaminant at its source, preventing dispersion of it into the general work area. Please refer to the ACGIH document, Industrial Ventilation, A Manual of Recommended Practices, most recent edition, for details.

#### Personal Respirators (NIOSH Approved):

If the exposure limit is exceeded, a half-face high efficiency dust/mist respirator may be worn for up to ten times the exposure limit or the maximum use concentration specified by the appropriate regulatory agency or respirator supplier, whichever is lowest. A full-face piece high efficiency dust/mist respirator may be worn up to 50 times the exposure limit, or the maximum use concentration specified by the appropriate regulatory agency or respirator supplier, whichever is lowest. For emergencies or instances where the exposure levels are not known, use a full-facepiece positive-pressure, air-supplied respirator. WARNING: Air-purifying respirators do not protect workers in oxygen-deficient atmospheres.

#### **Skin Protection:**

Wear impervious protective clothing, including boots, gloves, lab coat, apron or coveralls, as appropriate, to prevent skin contact

#### **Eve Protection:**

Use chemical safety goggles and/or full face shield where dusting or splashing of solutions

is possible. Maintain eye wash fountain and quick-drench facilities in work area.

#### Other Control Measures:

Eating, drinking, and smoking should not be permitted in areas where solids or liquids containing lead compounds are handled, processed, or stored. See OSHA substance-specific standard for more information on personal protective equipment, engineering and work practice controls, medical surveillance, record keeping, and reporting requirements. (29 CFR 1910.1025).

# 9. Physical and Chemical Properties

#### Appearance:

Small, white to blue-gray metallic shot or granules.

#### Odor:

Odorless.

#### Solubility:

Insoluble in water.

#### Density:

11.34

#### pH:

No information found.

#### % Volatiles by volume @ 21C (70F):

0

#### **Boiling Point:**

1740C (3164F)

#### **Melting Point:**

327.5C (622F)

#### Vapor Density (Air=1):

No information found.

#### Vapor Pressure (mm Hg):

1.77 @ 1000C (1832F)

#### Evaporation Rate (BuAc=1):

No information found.

# 10. Stability and Reactivity

#### Stability:

Stable under ordinary conditions of use and storage.

#### **Hazardous Decomposition Products:**

Does not decompose but toxic lead or lead oxide fumes may form at elevated temperatures.

## Hazardous Polymerization:

Will not occur.

#### Incompatibilities:

Ammonium nitrate, chlorine trifluoride, hydrogen peroxide, sodium azide, zirconium, disodium acetylide, sodium acetylide and oxidants.

## **Conditions to Avoid:**

Heat, flames, ignition sources and incompatibles.

# 11. Toxicological Information

#### Toxicological Data:

Investigated as a tumorigen, mutagen, reproductive effector.

## Reproductive Toxicity:

Lead and other smelter emissions are human reproductive hazards. (Chemical Council on Environmental Quality; Chemical Hazards to Human Reproduction, 1981).

#### Carcinogenicity:

EPA / IRIS classification: Group B2 - Probable human carcinogen, sufficient animal evidence.

\Cancer Lists\			
	NTP	Carcinogen	
Ingredient	Known	Anticipated	IARC Category
Lead (7439-92-1)	No	No	2B

# 12. Ecological Information

#### **Environmental Fate:**

When released into the soil, this material is not expected to leach into groundwater. This material may bioaccumulate to some extent.

#### **Environmental Toxicity:**

No information found.

**LEAD METAL** 

# 13. Disposal Considerations

Whatever cannot be saved for recovery or recycling should be managed in an appropriate and approved waste facility. Although not a listed RCRA hazardous waste, this material may exhibit one or more characteristics of a hazardous waste and require appropriate analysis to determine specific disposal requirements. Processing, use or contamination of this product may change the waste management options. State and local disposal regulations may differ from federal disposal regulations. Dispose of container and unused contents in accordance with federal, state and local requirements.

# 14. Transport Information

Not regulated.

# 15. Regulatory Information

\Chemical Inventory Sta Ingredient		mcan	E.C.	T	7
Lead (7439-92-1)		Yes	Yes	Yes	Yes
\Chemical Inventory Sta	tus - Part 2\				
Ingredient		Korea			Phil.
		Yes	Yes	No	
Lead (7439-92-1) \Federal, State & Inter:	national Regulat	ions -	Part 1	L\	
\Federal, State & Inter	-SAI RQ	RA 302- TPQ	Lis	,-SAR	 A 313 mical Cato
\Federal, State & Inter	-SAI RQ 	RA 302- TPQ	Lis	SAR st Che	A 313 mical Cato
\Federal, State & Inter	-SAI RQ  No national Regulat	RA 302- TPQ  No	Lis Yes Part 2	SAR st Che	A 313 mical Cato No SCA-

#### **Prop 65:**

Reactivity: No

THIS PRODUCT CONTAINS CHEMICALS KNOWN TO THE STATE OF CALIFORNIA TO CAUSE CANCER AND BIRTH DEFECTS OR OTHER REPRODUCTIVE HARM.

Australian Hazchem Code: No information found.

Poison Schedule: S6

#### WHMIS:

This MSDS has been prepared according to the hazard criteria of the Controlled Products Regulations (CPR) and the MSDS contains all of the information required by the CPR.

## 16. Other Information

NFPA Ratings: Health: 3 Flammability: 1 Reactivity: 0

#### Label Hazard Warning:

POISON! DANGER! MAY BE FATAL IF SWALLOWED OR INHALED. CAUSES IRRITATION TO SKIN, EYES AND RESPIRATORY TRACT. NEUROTOXIN. AFFECTS THE GUM TISSUE, CENTRAL NERVOUS SYSTEM, KIDNEYS, BLOOD AND REPRODUCTIVE SYSTEM. POSSIBLE CANCER HAZARD. MAY CAUSE CANCER BASED ON ANIMAL DATA. Risk of cancer depends on duration and level of exposure.

#### **Label Precautions:**

Do not get in eyes, on skin, or on clothing. Do not breathe dust. Keep container closed. Use only with adequate ventilation. Wash thoroughly after handling.

#### Label First Aid:

If swallowed, induce vomiting immediately as directed by medical personnel. Never give anything by mouth to an unconscious person. If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. In case of contact, immediately flush eyes or skin with plenty of water for at least 15 minutes. Remove contaminated clothing and shoes. Wash clothing before reuse. In all cases, get medical attention.

#### **Product Use:**

Laboratory Reagent.

#### **Revision Information:**

Pure. New 16 section MSDS format, all sections have been revised.

#### Disclaimer:

Mallinckrodt Baker, Inc. provides the information contained herein in good faith but makes no representation as to its comprehensiveness or accuracy. This document is intended only as a guide to the appropriate precautionary handling of the material by a properly trained person using this product. Individuals receiving the information must exercise their independent judgment in determining its appropriateness for a particular purpose. MALLINCKRODT BAKER, INC. MAKES NO REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTIES OF



MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO THE INFORMATION SET FORTH HEREIN OR THE PRODUCT TO WHICH THE INFORMATION REFERS. ACCORDINGLY, MALLINCKRODT BAKER, INC. WILL NOT BE RESPONSIBLE FOR DAMAGES RESULTING FROM USE OF OR RELIANCE UPON THIS INFORMATION.

Prepared by: Strategic Services Division Phone Number: (314) 539-1600 (U.S.A.)